

In some cases, the lower bolt for the Multitool tensioner arm interferes with attachment of the miter table mounting bracket. If that is the case, it will be necessary to add a second washer under the head of the tensioner arm lower attachment bolt. We've included this black oxide coated washer with the miter table hardware kit.



Fig: 1 shows the lower bolt for tensioner arm interfering with miter table mounting bracket .

Fig: 2 shows the black oxide coated washer installed in addition to the standard washer.

