


Figure 1 - Base

Tav. 1 - Basamento

Distributed by: **Trick-Tools.com**

**Trick-Tools
75 Truman Road
Pella, IA 50219**

**Phone: 1-877-VAN-SANT
E-mail: sales@trick-tools.com**



Here at Trick Tools we believe that our customers deserve the best value in their tool and equipment purchases. We are constantly at work searching out a variety of high quality, high performance tools to offer at the best prices possible. Our commitment to you is that we will not offer "cheap junk" anywhere on our website. You, the customer, help us to evaluate our products constantly and as soon as an ongoing quality issue is uncovered we will correct it or discontinue that product immediately. We hope to earn your continued trust.




Figure 1 - BASE

	Qty
1) Sawframe Support, revolving	1
2) Screw TE M10x45	2
3) Nut M10, exagonal	2
4) Bearing 32007X	2
5) Sleeve	2
6) Bushing	1
7) Screw TBEI M5x16	2
8) Nut GUK M35	1
9) Splash Guard	1
10) Material Support, infeed	1
11) Screw TCEI M8x25	3
12) Round Plate	1
13) O-ring ID195X5.7W	1
14) Filter, coolant liquid	1
15) Tube	1
16) Screw TBEI M6x20	1
17) Connection 3/8", coolant liquid	1
18) Electropump, coolant liquid	1
19) Glass 3/8", coolant liquid level	1
20) Plug, coolant liquid drain	1
21) Screw M10x20	4
22) Washer M10	4
23) Lever, Sawframe miter lock/unlock	1
24) Screw TCEI M8x25	1
25) Washer d.18-8,5x1,6	2
26) Screw TCEI M6x15	1
27) Washer M6	1
28) Nut M6, exagonal	1
29) Vice Support	1
30) Screw TBEI M6x10	1
31) Screw TE M8x20	12
32) Washer M8	24
33) Nut M8, exagonal	12
34) Pedestal	1
35) Bench/Reservoir, coolant liquid	1



Figure 2 - Sawframe



Tav. 2 - Arco




Figure 2 - SAWFRAME

Qty

101) Sawframe	1
103) Bar, attachment for return spring	1
104) Shaft, sawframe articulation	1
105) Screw TCEI M10x25	2
106) Screw TCEI M10x40	2
107) Screw TCEI M8x30	2
108) Screw TCEI M6x20	4
109) Washer M6	2
110) Ring Nilos 32006X AV	2
111) Bearing 32006X	2
112) Flywheel, return	1
113) Nut GUK M30	1
114) Flywheel, motor	1
115) Washer, Large	1
116) Screw TE M12x20	1
117) Screw TCEI M6x10	2
118) Valve 1/8"	2
119) Block, blade tension	2
120) Screw M6x6	2
121) Screw TBEI M5x12	2
122) Washer 12-5,5x0,8	3
123) Blade Guard, blade-guide fixed	1
124) Screw TBEI M6x30	4
125) Pin, short eccentric	2
126) Bearing 608 2RS	4
127) Ring S10	4
129) Sawframe Cover	1
130) Washer	1
131) Blade	1
132) Screw M6x10	4
133) Bar, mobile blade-gurad	1
134) Screw M6x15	1
135) Screw TCEI M8x20	1
136) Block, mobile blade-guide	1
137) Blade Guard, blade-guide mobile	1
138) Screw TBEI M6x10	1
139) Support, electric box	1
140) Electric Box	1
141) Spring, sawframe return	1
142) Pin, spring attachment	1



Figure 3 - Sawframe and Vice



Tav.3 - Arco e morsa



Figure 3 - SAWFRAME and VICE


Qty

201) Motor 0,37/0,75 kW - 50Hz - 400V – 4P	1
202) Spline 6x6x40	1
203) Screw TCEI M10x20	1
204) Screw TCEI M10x25	2
205) Plastic Cover	1
206) Screw TCEI M10x25	4
207) Washer M10, elastic	4
208) Washer M6, elastic	4
209) Screw TE M6x20	4
210) Washer, large	1
211) Gear-Box G5A i=1/40	1
212) Spline 8x7x50	1
213) Shaft, motor flywheel	1
214) Spline 8x7x25	1
215) Bearing 6208 2RS	1
216) Screw TCEI M6x15	2
217) Connection 8x1/4"	1
218) Coolant Distributor, 3 ways	1
219) Connection 6x1/8"	4
220) Tube Ø 6 L=240	1
221) Tube Ø 6 L=800	1
222) Screw TBEI M5x16	1
223) Screw TCEI M8x20	3
224) Washer M8, elastic	3
225) Shaft, return flywheel	1
226) Screw TBEI M5x10	2
227) Plate, blade tension	1
228) Pin Ø 5x38	2
229) Block, bkade tension	1
230) Screw TCEI M8x20	3
231) Block, fixed	1
232) Support, brush	1
233) Screw TBEI M6x10	2
234) Brush 50-14x6, blade cleaning	1
235) Nut M6, exagonal	1
236) Screw TE M6x30	1
237) Washer 18-6,5x1,5	2
238) Washer 13-6,5x0,8	2
239) Washer M10-20x2	1
240) Screw TCEI M10x50	1
241) Screw senza testa M8x5	1
242) Block	1
243) Rivet	1
244) Scale	1

continued



245) Nut M8, exagonal	1
246) Screw TE M8x45	1
247) Nut M16, exagonal	1
248) Pin M16, blade tension	1
249) Cup Spring Ø 31,5-16,3x1,8	14
250) Notch, reference	1
251) Bearing 51203	1
252) Handwheel M12, blade tension	1
253) Grip, sawframe lever	1
254) Push-Button, motor start	1
255) Cable, push-button connection	1
256) Lever, sawframe movement.....	1
257) Screw TSEI 6X12	2
258) Vice Jaw	1
259) Vice	1
260) Screw TCEI M6X110	2
261) Screw, vice lead	1
262) Spring	1
263) Bushing, vice	1
264) Vice Lever	1
265) Bearing AX3047XCP	1
266) Pin Ø 5x35, elastic	1
267) Handwheel, vice lead	1
268) Protection, bearing	1
269) Countervise	1
270) Screw TCEI M10X30L	1
271) Washer M10	1
272) Right Jaw	1
273) Screw TCEI M6X15	1
274) Screw M8X10, exagonal	1
275) Shaft, sawframe revolving	1
276) O-ring 19,8x2,4	1
277) Handle, bar-stop	1
278) Rod, bar-stop.....	1
279) Pointer, bar-stop.....	1
280) Scale, bar-stop	1
281) Body, bar-stop	1
282) Left Jaw	1
283) Screw TSEI M6x15	1



ELECTRIC COMPONENTS

- | | |
|---------------------------|-----|
| 1) Transformer | TC1 |
| 2) Aux. Relay | KA |
| 3) Remote Switch..... | KM1 |
| 4) Fuse cartridge | FU1 |
| 5) Fuse cartridge | FU2 |
| 6) Blade Speed Switch. | |
| 7) Push-Button, Ready. | |
| 8) Emergency Push-Button. | |




11 ELECTRIC PLANS

LIST OF ELECTRIC COMPONENTS

ZIP 22 - Three-phase 400 Volt 50Hz. Drw E01-1. dd 17/11/2011.

Ref.	Description	Technical Data	Qty	Make	Code
FU1	Fuse Cartridge	3 Pole 32A 600V	1	Weber	PCH 3X38
	Fuse, Line Protection	FUS CH 10X38 12AGG	3	Weber	CH10X38 10A AM
FU2	Fuse Cartridge	1 Pole 32A 600V	1	Weber	PCH 1X38
	Fuse, Aux. Protection	FUS CH 10X38 1 600V	1	Weber	CH10X38 1A AM
TC1	Transformer	20VA OUT 24 V	1	METH	P 330/400 S0-24
C.M.	Pole Commutator	16A 690V	1	Giovenzana	P01606360S009
KM1	Remote Switch	9A NO 24VAC	1	A.B.	100-K09KJ10
FR1	Thermal Relay, Motor Protection	3,5 - 4,8A	1	A.B.	193-KB48
KA	Aux. Relay	1 CONTACT 250V 10A +base	1	FINDER	ART 403180024 VAC
-	Base, Finder Relay	for FINDER Relay	1	FINDER	ART. 40-9563
HL1	Pilot Light	2W BAS 9	1	REER	30V 2Watt
SB1	Emergency Push-Button	with Lock	1	A.B.	800 FP-MT 44
-	Base of Push-Button	D.22	1	A.B.	800F-ALP
-	N.C. Contact	10A 600V	1	A.B.	800F-X01
SQ1	Micro-switch, sawframe protection	6A 250V.	1	LOVATO	KB N2 L02PV155
SQ2	Micro-switch, Gripswitch	4A 250V.	1	CROUZET	E.F. 83161.1
M1	Motor, Blade Drive	kW 0,55-1 1400/2800 rpm	1	JIUH DAH	
M2	Motor, Electropump	kW 0,05 H85 single-phase	1	SAP	2 poles
X1	Terminals, connection	Section 2,5	3	CONTACTCLIP	1574 2
	Plastic Box, Elettrocablaggi	230E0097/10	1	STANPLAST	
	Film, Control Panel	220X0181	1	Tecnotarghe	220X0181
	Box, Electric Components	Elettrocablaggi	1		TIPO D.SPECIAL



**LIST OF ELECTRIC COMPONENTS**

ZIP 22 - Single-phase 400 Volt 50Hz. / 110 Volt 60 Hz. dd 12/03/2012.

Ref.	Description	Technical Data	Qty	Make	Code
FU1	Fuse Cartridge	2 Pole 32A 600V	1	Weber	PCH 2X38
	Fuse, Line Protection	10X38 16A 600V	2	Weber	CH10X38 16A AM
FU2	Fuse Cartridge	1 Pole 32A 600V	1	Weber	PCH 1X38
	Fuse, Aux. Protection	10X38 1A 600V	1	Weber	CH10X38 1A AM
TC1	Transformer	30VA OUT 24 V	1	F.M.T.	P 0/110 60 Hz S24
C.M.	Pole Commutator	20A 690V	1	Giovenzana	P0200003R010
KM1	Remote Switch	25A NO 24VAC	1	A.B.	100-C23 KJ10
KA	Aux. Relay	1 CONTACT 250V 6A	1	FINDER	ART 403180024 VAC
-	Base, Finder Relay	for FINDER Relay	1	FINDER	ART. 40-9563
S.B. 2	Push-Button, Light		1	A.B.	AB 800 LF7
HL1	Pilot Light	2W BAS 9	1	REER	30V. 2 WATT
SB1	Emergency Push-Button	with Lock	1	A.B.	800FP-MT 44
"	Base, Push-Button	D.22	2	A.B.	800F-ALP
"	Contact N.C.	10A 600V.	1	A.B.	800F-X01
SB2	Contact N.O.	10A 600V.	1	A.B.	800F-X10
SQ1	Micro-switch, sawframe protection	8A 400V.	1	Q.k.S 8	
SQ2	Micro-switch, Gripswitch	4A 250V.	1	CROUZET	E.F. 83161.1
M1	Motor, Blade Drive	kW 0,91400rpm	1	TESSARO	FC B 14 80 IP54
M2	Motor, Electropump	kW 0,05 H85 single-phase	1	SAP	SH2 IP54
X1	Terminals, connection	Section 2,5 twin	2	A.B.	
	Plastic Box, Elettrocablaggi	230E0009/10	1	STANPLAST	
	Film, Control Panel	220X0340	1	Tecnotarghe	220X0340
RIF.	Gear-Box	1/15 80 B14	1	S.T.M.	RMI 50
C.	Condenser	50mf/31mf	1+1	TESSARO	

